



PW Laboratories, Inc.
 6544 Fremont Road - East Syracuse, New York 13057
 Office 315.437.1420 ~ Fax 315.503-3058 ~ pwlabinc@hotmail.com

Sieve Analysis of Soil / Aggregate

Project Title: Laboratory Testing

Report #: 1

Project #: L-21033

Test Method: ASTM C117 & C136

Report Date: January 11, 2022

Source:		Sieve Size - Percent Passing Sieve														
Lab I.D. #	Sample I.D.	3"	2"	1 1/2"	1"	3/4"	1/2"	3/8"	1/4"	#4	#10	#30	#40	#60	#100	#200
41615	Type 1 Crushed Limestone	100	98.0	92.8	80.9	71.7	55.3	47.7	35.3	28.4	18.0	11.1	9.5	8.3	7.4	6.6
	NYSDOT Specifications Item #733-04A Type 1	100	90-100	-	-	-	-	-	30-65	-	-	-	5-40	-	-	0-10

Sample mass, as received, meets minimum mass requirements of test method:

Yes No

Prewashed

Performed By: Mark Santorelli

Checked By: Patrick Edmiston

Entire Sample

Remarks:

Mass Retained on #200 Only

Not Prewashed: