



PW Laboratories, Inc.
 6544 Fremont Road - East Syracuse, New York 13057
 Office 315.437.1420 ~ Fax 315.503-3058 ~ pwlabinc@hotmail.com

Sieve Analysis of Soil / Aggregate

Project Title: Laboratory Testing

Report #: 2

Project #: L-21033

Test Method: ASTM C117 & C136

Report Date: January 11, 2022

Source:		Sieve Size - Percent Passing Sieve													
Lab I.D. #	Sample I.D.	2"	1 1/2"	1"	3/4"	1/2"	3/8"	1/4"	#4	#10	#30	#40	#60	#100	#200
41616	Type 2 Crushed Limestone	100	100	85.8	75.4	60.6	52.9	40.2	33.1	20.0	11.4	9.6	8.3	7.4	6.5
	NYSDOT Specifications Item #733-04A Type 2	100	-	-	-	-	-	25 - 60	-	-	-	5 - 40	-	-	0 - 10

Sample mass, as received, meets minimum mass requirements of test method:

Yes No

Prewashed

Performed By: Mark Santorelli

Checked By: Patrick Edmiston

Entire Sample

Remarks:

Mass Retained on #200 Only

Not Prewashed: